



4-TIER ORNAMENT Counter Display Assembly

To ensure trouble-free operation, please read and follow all instructions carefully.

PARTS LIST:

- A. Base
- B. 1 large pole section 16"
- C. 1 small pole section 13.5"
- D. Header/topper
- E. Cardboard header card
- F. 4 sets of display arms
- G. 4 sleeves with wing-nut screws

TO ASSEMBLE:

Assemble the display in the order shown on the diagram starting with the base first.

1. Place the base (A) on a flat, stable surface.
2. Insert the large pole section (B) into the base.
3. Slide first sleeve (G) onto the large pole section (B) and position accordingly to the ornament's height.
4. Position the first set of display arms (F) on top of the first sleeve.
5. Insert the small pole section (C) onto the receiver end of the large pole section (B).
6. Slide the remaining sleeves (G) and display arms (F) onto the small pole section (C). Distribute space between the display arms according to the height of the ornament and hanger. Stagger the display arms to allow for tangle free display.
7. Insert the header (E) into the small pole section to complete the display assembly.

CAUTION:

- Some sections may have a snug fit and slight force may be necessary in order to have the pieces fit together correctly.
- Distribute product evenly to prevent the display from tipping or leaning.

